ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0121, W0064, W0066, W0119, W0062, W0068	NA	Vinayakanagar Air force
Segment No.	**Total Length (m)**	
11/C-W0121/S033415	234.84	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	99.94	77.545088	13.082456	77.544373	13.082052	W0062	DEAD END
2	36.32	77.544428	13.082324	77.544713	13.082150	W0119	W0121
3	48.05	77.544552	13.082516	77.544946	13.082317	W0119	W0121
4	50.53	77.544668	13.082695	77.545080	13.082481	W0119	W0121

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Development work at Vinayakanagar Air force in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Development work at Vinayakanagar Air force in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000040
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/60/2015-16	29/04/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/12/2015	14/12/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00

Phone No.	E-Mail ID
9731567144	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH

Date of Inspection	Remarks
18/03/2017	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0121, W0064, W0066, W0119,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	YARAPPA REDDY	18/03/2017	17/04/2017	COMPLETED
AEE	MAHADEV	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0121, W0064, W0066, W0119,